## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422


## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422

## ADHESIVE APPLICATION INSTRUCTIONS FOR OPTIMAL PERFORMANCE

1. Apply adhesive at temperatures above 50°F (10°C).
2. Clean the surface of the magnet with the blue stripe for application of the adhesive tape (this is the weaker side of the magnet.)
3. Remove paper on one side of double-sided tape and press the exposed adhesive side down onto the magnet as shown using at least 15psi of pressure. Allow a minimum of 20 minutes for adhesive to bond to magnetic cup before applying the other side of adhesive tape to your item.
4. Allow all adhesive to bond for 24 hours prior to use.

Bond times/strength: 20min/50%, 60min/75%, 24hrs/90+%



Industrial Magnetics, Inc. Manual 900422